Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	2	("5953243").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 08:44
S2	2	("6282689").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/05 13:18
S3	2	("6330637").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/05 13:20
S5	2	("6330696").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/05 13:22
S6	2	("6493843").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/05 13:27
S7	0	711/5,115 or 714/5,42	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/05 13:28
58	2769	713/1-2.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 08:44
S9	804	S8 and firmware	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:00

S10	778	S9 and memory	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF .	2005/10/11 08:45
S11	408	S9 and non-volatile	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 08:46
S12	14	S11 and (fault same storage)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 08:51
S13	118	S11 and boot near2 code	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 08:56
S14	24	S13 and error with code	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:49
S15	29	S13 and error same code	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 08:52
S16	29	S11 and (boot near2 code same read same memory)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 08:57
S17	11	S11 and (boot near2 code with read with memory)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 08:58

, 			LIC DCDLID:	OD	OFF	2005/10/11 09:50
S18	5	S11 and (boot near2 code same remap\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 08:59
S19	0	S9 and remap\$4 near2 bits	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:00
S20	29	S9 and remap\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:01
S21	14	S9 and (remov\$3 same bits)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:04
S22	1410	firmware and (remov\$3 same bits)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:06
S23	12	firmware and (remap\$4 near2 bits)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:05
S24	0	firmware same (remap\$4 near2 bits)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:05
S25	59680	firmware	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:06

S26	2	S25 and (remov\$3 with bits same non-volatile)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:09
S27	742	jeddeloh	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:09
S28	19	S27 and firmware	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:16
S29	1666	firmware and (memory near2 bits)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:19
S30	31	firmware and (remov\$3 same memory near2 bits)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:28
S31	0	firmware and (remov\$3 same memory near2 bits same error)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:19
S32	1	firmware and (boot near2 code same error near2 handling near2 code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:29
S33	1	firmware and (boot near2 code) and (error near2 handling near2 code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:31

•						
S34	118	firmware and (boot near2 code) and (error near2 code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:29
S35	25	(firmware same boot near2 code) and (error near2 code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:30
S36	57	firmware and error near2 handling near2 code	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:55
S37	1	S36 and boot near2 code	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:31
S39	18	firmware and (boot near2 code) and (error near2 correction near2 code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 09:31
S40	1	firmware same (boot near2 code) same (error near2 correction near2 code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:52
S41	78	cepulis.in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/11 11:20
S42	2	"6496945".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 07:49

Cac	F704	firmulare come (CDL) or control = di	US-PGPUB;	OR	OFF	2005/10/12 08:00
S46	5794	firmware same (CPU or central adj processing adj unit)	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OK .	OI I	2003/10/12 00:00
S47	698	S46 same coupl\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:00
S48	73	S47 same module	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:00
S49	44	S48 same memory	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:04
S50	3447	firmware with(CPU or central adj processing adj unit)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:00
S51	1305	S50 with memory	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:01
S52	36	S51 with error	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:01
S53	10	S49 same interface	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:10

•						
S54	69473	ROM same interface	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:11
S55	18233	ROM same interface same CPU same memory	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:12
S56	18804	(ROM or microcontroller or micro-controller) same interface same CPU same memory	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:12
S57	1022	(ROM or microcontroller or micro-controller) same memory near2 interface same CPU	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:13
S58	120	(ROM or microcontroller or micro-controller) same memory near2 interface same CPU same coupl\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:13
S59	125	(ROM or microcontroller or micro-controller or firmware) same memory near2 interface same CPU same coupl\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:16
S60	1	S59 same boot near2 code	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:14
S61	4	(boot near2 code) same (error near2 correction near2 code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:56

				<del></del>		
S62	57	firmware and error near2 handling near2 code	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:55
S63	1	S62 and boot near2 code	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:55
S64	77	(boot near2 code) and (error near2 correction near2 code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:58
S65	18	S64 and firmware	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:56
S66	615	(boot near2 code) and (error with code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:58
S67	2610	(boot near2 code) and (error near2 (handling or correction) code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:59
S68	2610	(boot near2 code) and ((error near2 (handling or correction)) code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 08:59
S69	2288621	boot near2 code and error near2 (handling or correction) code	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 09:00

•						
S70	81	(boot near2 code) and (error near2 (handling or correction) near2 code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 09:03
S71	35	boot same (error near2 (handling or correction) near2 code)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 09:04
S72	40	boot same (error near2 (handling or correction) near2 code\$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 09:10
S73	59	error near2 handling same boot	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 12:47
S74	2	"20020002690".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 11:13
S75	2	"20050028038"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 12:30
S76	17	"6052798"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 11:22
S77	12	"6496945"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 11:22

•						
S78	76	range near2 bit\$1 same DRAM	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 12:31
S79	50	range near2 bit\$1 with DRAM	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 12:33
S80	1	range near2 bit\$1 with DRAM with tag	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 12:33
S81	133	(range or tag or history) near2 bit\$1 with DRAM	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 12:34
S82	85	(tag or history) near2 bit\$1 with DRAM	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 12:38
S83	3	history near2 bit\$1 with DRAM	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 12:40
S84	11664068	(device or unit or module) indentifier near2 bit	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 12:42
S85	0	memory near2 indentifier near2 bit	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 12:42

S86	5	indentifier near2 bit	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 12:45
S87	1	(device or unit or module) near2 indentifier near2 bit	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 12:42
S88	1215	history near2 bit\$1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 12:46
S89	14	error near2 handling same boot same firmware	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 12:47
S90	2454	bit\$1 near2 failure	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 14:33
S91	87	S90 near5 time	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 13:55
S92	178	S90 with time	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 13:55
S93	50912	"714"/\$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 13:55

•						
S94	503	S93 and S90	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 14:13
S95	503	S93 and bit\$1 near2 failure	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 14:13
S96	178	S90 with time	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 14:16
S97	16	S90 with range	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 14:30
S98	7	S97 and S93	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 14:17
S99	21318	(time or instance) near2 failure	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 14:31
S10 0	45	S90 with DRAM	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 14:32
S10 1	133	S90 same occurrence\$1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 14:33

•						
S10 2	1	S101 same recent	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF <sub>.</sub>	2005/10/12 14:34
S10 3	47	S101 same time	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 14:39
S10 4	9	history near2 (bit\$1 or flag\$1 or field\$1) near2 failure	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/12 14:59
S10 5	0	time of last failure	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/12 14:59
S10 6	57	time near2 last near2 failure	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/12 15:00
S10 7	1	S106 near2 bit\$1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/12 15:00
S10 8	1818	(last or recent) near2 fail\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/12 15:01
S10 9	26	S108 near2 (bit\$1 or tag\$1 or flag\$1 or byte\$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/12 15:15

•						
S11 0	10	history with fail\$3 near2 log	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/12 15:42
S11 1	0	S110 same bit\$1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/12 15:16
S11 2	46	fail\$3 near2 log same bit\$1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/12 15:42
S11 3	20	fail\$3 near2 log with bit\$1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/12 16:05
S11 4	1	fail\$3 near2 log with bit\$1 same history	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/12 15:43
S11 6	68	fail\$3 near2 log with (tag\$1 or field\$1 or flag\$1 or byte\$1 or header\$1 or counter\$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/13 09:45
S11 7	2	fail\$3 near2 log with (tag\$1 or field\$1 or flag\$1 or byte\$1 or header\$1 or counter\$1) same DRAM	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/12 16:04
S11 8	76	fail\$3 near2 (log or record or list) with bit\$1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/13 08:27

S11 9	1	fail\$3 near2 (log or record or list) with bit\$1 same history	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/13 08:28
S12 0	55	fail\$3 near2 log with (tag\$1 or field\$1 or flag\$1 or byte\$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/13 09:45
S12 1	2	fail\$3 near2 log with (tag\$1 or field\$1 or flag\$1 or byte\$1 or header\$1 or counter\$1) same (timestamp or time near2 stamp)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/13 09:53
S12 2	37	"4506362"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/13 09:55
S12 3	36	"4535455"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	OFF	2005/10/13 09:55
S12 4	15	("4964129").URPN.	USPAT	OR	OFF	2005/10/13 09:58
S12 5	18	("4964130").URPN.	USPAT	OR	OFF	2005/10/13 10:59
S12 6	2	"6493843"	USPAT	OR	OFF	2005/10/13 10:59
S12 7	2	"20050028038"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/13 16:21
S12 8	890	logical near2 analysis	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/13 16:21

S12 9	0	S127 same histroy	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/13 16:22
S13 0	0	S127 same history	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/13 16:22
S13 1	7	S128 same history	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/13 16:22